

**CITY OF BALTIMORE WET WEATHER CONSENT DECREE  
SMOKE AND DYED WATER TESTING FORM**

Page 1 of 8

Sewershed: OUTFALL

Company: REI/DRAYCO

Date: 09/30/2008

Test Type: SMOKE

Ground Condition:  
Dry: **X** Damp: \_ Wet: \_


Supervisor: E.R.

Manhole ID: S49II\_032MH

Test ID: S1039-011

Notifications Made: **X** (Residents, Fire, 311)

Field Sketch: (Show all manholes with numbers, blower placement location, sandbag or isolation locations, street names, building addresses and locations, defect locations and photograph numbers)



[illegible]

CITY OF BALTIMORE  
SMOKE TESTING OBSERVATION SUMMARY  
OUTFALL SEWERSHED  
BALTIMORE CITY PROJECT 1039  
REI/DRAYCO

Unique Test ID: S1039-011	Date: 09/30/2008	Manhole ID: S49II_032MH
Defect No: OB01	Supervisor: E.R.	Basin: Outfall
Location: 2821 E. FEDERAL ST.		
Source Type: 03 Cleanout	Sector: 02 Private	
Location: 07 Yard - Front	Severity: 03 Moderate	Drainage Area: 1 ft <sup>2</sup>
Comments: Smoke is coming from a cleanout with a broken cap at 2821 E. Federal Ave.		

SMOKE TEST PHOTOGRAPHS



Photograph No: OB01-P01  
Filename: S1039-011\_OB01-P01.jpg



CITY OF BALTIMORE  
SMOKE TESTING OBSERVATION SUMMARY  
OUTFALL SEWERSHED  
BALTIMORE CITY PROJECT 1039  
REI/DRAYCO

Unique Test ID: S1039-011	Date: 09/30/2008	Manhole ID: S49II_032MH
Defect No: OB02	Supervisor: E.R.	Basin: Outfall
Location: 2839 E. FEDERAL ST.		
Source Type: 03 Cleanout	Sector: 02 Private	
Location: 07 Yard - Front	Severity: 02 Trace	Drainage Area: 1 ft <sup>2</sup>
Comments: Smoke is coming from above grade cleanout with a broken cap at 2839 E. Federal St.		

SMOKE TEST PHOTOGRAPHS



Photograph No: OB02-P01  
Filename: S1039-011\_OB02-P01.jpg



CITY OF BALTIMORE  
SMOKE TESTING OBSERVATION SUMMARY  
OUTFALL SEWERSHED  
BALTIMORE CITY PROJECT 1039  
REI/DRAYCO

Unique Test ID: S1039-011	Date: 09/30/2008	Manhole ID: S49II_032MH
Defect No: OB03	Supervisor: E.R.	Basin: Outfall
Location: 1506 KENHILL AVE.		
Source Type: 03 Cleanout	Sector: 02 Private	
Location: 07 Yard - Front	Severity: 03 Moderate	Drainage Area: 1 ft <sup>2</sup>
Comments: Smoke is coming from an above grade cleanout in front of 1506 Kenhill Ave.		

SMOKE TEST PHOTOGRAPHS



Photograph No: OB03-P01  
Filename: S1039-011\_OB03-P01.jpg



CITY OF BALTIMORE  
SMOKE TESTING OBSERVATION SUMMARY  
OUTFALL SEWERSHED  
BALTIMORE CITY PROJECT 1039  
REI/DRAYCO

Unique Test ID: S1039-011	Date: 09/30/2008	Manhole ID: S49II_032MH
Defect No: OB04	Supervisor: E.R.	Basin: Outfall
Location: 1507 KENHILL AVE.		
Source Type: 03 Cleanout	Sector: 02 Private	
Location: 07 Yard - Front	Severity: 02 Trace	Drainage Area: 1 ft <sup>2</sup>
Comments: Smoke is coming from an above grade cleanout with a broken cap at 1507 Kenhill Ave.		

## SMOKE TEST PHOTOGRAPHS



Photograph No: OB04-P01  
Filename: S1039-011\_OB04-P01.jpg



CITY OF BALTIMORE  
SMOKE TESTING OBSERVATION SUMMARY  
OUTFALL SEWERSHED  
BALTIMORE CITY PROJECT 1039  
REI/DRAYCO

Unique Test ID: S1039-011	Date: 09/30/2008	Manhole ID: S49II_032MH
Defect No: OB05	Supervisor: E.R.	Basin: Outfall
Location: 1513 KENHILL AVE.		
Source Type: 03 Cleanout	Sector: 02 Private	
Location: 07 Yard - Front	Severity: 03 Moderate	Drainage Area: 1 ft <sup>2</sup>
Comments: Smoke is coming from above grade cleanout with a broken cap at 1513 Kenhill Ave.		

SMOKE TEST PHOTOGRAPHS



Photograph No: OB05-P01  
Filename: S1039-011\_OB05-P01.jpg

CITY OF BALTIMORE  
SMOKE TESTING OBSERVATION SUMMARY  
OUTFALL SEWERSHED  
BALTIMORE CITY PROJECT 1039  
REI/DRAYCO

Unique Test ID: S1039-011	Date: 09/30/2008	Manhole ID: S49II_032MH
Defect No: OB06	Supervisor: E.R.	Basin: Outfall
Location: 1512 N. LINWOOD AVE.		
Source Type: 03 Cleanout	Sector: 02 Private	
Location: 07 Yard - Front	Severity: 03 Moderate	Drainage Area: 1 ft <sup>2</sup>
Comments: Smoke is coming from above grade cleanout with a broken cap at 1512 N. Linwood Ave.		

SMOKE TEST PHOTOGRAPHS



Photograph No: OB06-P01  
Filename: S1039-011\_OB06-P01.jpg